

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 2 290 BROADWAY NEW YORK, NY 10007-1866

SEP 2 5 2008

Ms. Mary Lou Capichioni Director Remediation Services Corporate Environmental Services The Sherwin-Williams Company 101 Prospect Avenue, N.W. Cleveland, OH 44115-1075



Re:

Sediment Sample Collection for SEM/AVS Analysis (October 12, 2006)

Sherwin-Williams Sites

AOC Index Number: No. II CERCLA-02-99-2035

Gibbsboro Borough, Voorhees Township and Lindenwold Borough, New Jersey


Dear Ms. Capichioni:

The United States Environmental Protection Agency (EPA) has reviewed the October 12, 2006 (proposed sampling plan for) *Sediment Sample Collection for SEM/AVS Analysis* (within Hilliards Creek) submitted to EPA by The Sherwin-Williams Company (SWC). EPA offers the following comments on the October 12, 2006 submittal; in addition, comments by the New Jersey Department of Environmental Protection (NJDEP) are incorporated.

1. The draft submittal proposes the collection of 16 sediment samples from Hilliard Creek (with a range of lead and total organic carbon concentrations) for simultaneously extracted metals/acid volatile sulfides (SEM/AVS) analysis. Please note, additional samples should also be collected and analyzed for TAL metals and total organic carbon (TOC). The rationale for SEM/AVS analysis is to assist in determining the bioavailability of certain metals (i.e., lead, copper, cadmium, zinc, and nickel). It should be noted that due to uncertainties associated with this analysis, SEM/AVS results should not substitute for the following: bulk sediment chemical analyses; toxicity tests; benthic macroinvertebrate surveys; and/or tissue bioassays when assessing sediment quality – however, SEM/AVS results may aid in interpretation of these studies.

While AVS is effective in binding divalent metals in anoxic sediments, it is generally less applicable to the more oxic conditions in the upper 2 cm of sediments, considered the primary biotic zone (benthic organisms require oxygen and would not be present in its absence). Additionally, use of the SEM/AVS approach requires that the sediments are never disturbed or changed from the parameters examined to make the ratio calculations. Therefore the method's ability to predict toxicity is limited and there are uncertainties associated with seasonality, temperature and pH. Flood events, excavation, etc., may cause sediment disturbance and volatile sulfide oxidation, potentially resulting in the release of a "slug" of metals to the environment.

cc: Lynn Arabia, Foster Wheeler Environmental John Doyon, NJDEP



As you are aware, EPA (along with staff from Weston Solutions) proposed sample locations as part of the future residential soil sampling activities scheduled to occur at each of the residential homes for which signed access agreements had been granted. To summarize, each home is scheduled to have 10 soil samples collected from their property. The purpose of the soil sampling activity is to determine if select residents are at risk to contaminants from Hilliard's Creek (Creek), due to the periodic flooding of Hilliard's Creek (through natural deposition), or if any specific activities by the resident have lead to the unknowing placement of contaminated Creek material being placed onto their property.

In order to assess the likelihood of either of these scenarios, interviews with each resident was performed, both in order to gain any historical knowledge of their property and also to learn what areas of the property (near the Creek) they currently frequent. In the absence of any historical knowledge provided to EPA and Weston Solutions, sample locations were selected based on low-lying areas near the Creek, again biasing them towards areas that were frequented by the resident (this included both garden areas or child play-areas).

You indicated during the March 20, 2007 conference call that the SWC intended to submit written protocols for residential soil sampling. We suggest, based on our current understanding of the conditions near the Creek and discussions with the EPA Risk Assessor, that the following intervals be sampled at each of the 10 soil sample locations: 0-6" interval (to be analyzed for all parameters, except VOCs) and the 18-24" interval (to be analyzed for full TAL/TCL). In addition, the Sherwin-Williams Company has expressed the desire to collect additional samples for lead analysis from the 0-1" interval. The Sherwin-Williams Company is permitted to conduct this sampling; however, this data will not be used by the EPA Risk Assessor during our assessment.



Klimcsak.Raymond@epamail .epa.gov 06/19/2007 01:16 PM

To lynn.arabia@tteci.com

CC

bcc

Subject Fw: residential soil sampling

also....see below, I think I may have bcc:ed you on this awhile ago, but this is the change that I requested for the res. sampling.

---- Forwarded by Raymond Klimcsak/R2/USEPA/US on 06/19/2007 01:16 PM

Raymond Klimcsak/R2/USEP A/US

То

03/26/2007 03:30 PM Mary Lou Capichioni

CC

Subject

residential soil sampling


Mary Lou,


Please take a look at my write-up (below) regarding EPA's proposal for sampling depth intervals when performing the residential soil sampling program at the Gibbsboro Sites. It's a combination of a few things, that are not driven by the "depth-to-water".

If you feel that the proposal is appropriate, I would suggest including the protocol along with the pdf. sampling maps for each residential property.

By the way, I received a copy of the figures (and CD) for the White Sands Branch and Hillliard's Creek sampling data. Do you know if a copy was sent to the NJDEP? I'm also not sure if Mindy Pensak (EPA, Edison) and Lynn Arabia received a copy? I think they look fine, I wasn't sure if you were looking for my comments. I could use several extra copies, but will let you know how many after I hear back from you.


thanks, Ray









PROPERTY OWNER: Charles I & Barbara S Ropka DATE: February 13, 2007		
RESIDENCE ADDRESS: 8 Steven Drive, Voorhees, NJ INTERVIEWER: P. Austin		
1. How long have you owned or rented the property in question?		
The resident reported owning the property for twenty eight years (since 1979).		
2. During the period you have owned your property, have you observed any discolored soils, stressed vegetation or any unusual odors?		
No.		
3. Has there been any sampling conducted at the property? Yes.		
4. If so, who conducted the sampling, for what purposes was this conducted and are the sample results available?		
Transect samples were collected as part of the Gibbsboro Remedial Investigation by Weston.		
5. Has there been any remedial, construction, landscaping, clearing or any other earth disturbing activities conducted at the property?		
No.		
6. Can you provide the details of any earth disturbing activities described above if any were conducted, and provide any maps, drawings or design plans if available?		
N/A.		





PROPERTY OWNER: Charles I & Barbara S Ropka	DATE: February 13, 2007		
RESIDENCE ADDRESS: 8 Steven Drive, Voorhees, NJ	INTERVIEWER: P. Austin		
7. If any earth moving activities were conducted empty containers, discolored soils, or foul odd	at the property, was anything unusual discovered such ors?		
No.			
8. Has any additional soil/fill been introduced to	the property or low lying area filled?		
No.			
9. Have any structures been established on the proto to the home?	roperty (i.e. new deck or shed) or any extension added		
No.			
10. Are there any plans to conduct any landscaping, tree removal, extensions, and/or other construction activities in the near or distant future at the property?			
Not at this time.			
11. Other notes/comments:			
Bruin (farmer) was the previous owner of the	property.		
Please note that this property is adjacent to the age-restricted community in Glenview Way Ea	main beaver dam that is constructed behind the st.		







PROPERTY OWNER SURVEY QUESTIONNAIRE

PROPERTY OWNER: Doris N Evans DATE: February 13, 2007

RESIDENCE ADDRESS: 10 Steven Drive, Voorhees, NJ INTERVIEWER: P. Austin

1. How long have you owned or rented the property in question?

The resident reported owning the property for twenty eight years (since 1979).

2. During the period you have owned your property, have you observed any discolored soils, stressed vegetation or any unusual odors?

Not to the knowledge of the homeowner. She only goes on the deck to add food to the bird feeders and does not venture into the backyard very often. Also, no intrusive activities have been conducted in recent years.

3. Has there been any sampling conducted at the property?


Yes. Homeowner reported that samples were collected back in 2000 or so, however the resident was not clear by whom.

4. If so, who conducted the sampling, for what purposes was this conducted and are the sample results available?

Homeowner did not know who collected the samples in the 2000 time-frame.

5. Has there been any remedial, construction, landscaping, clearing or any other earth disturbing activities conducted at the property?

The last construction activity conducted at the property included building a deck some 28 years ago.








PROPERTY OWNER SURVEY QUESTIONNAIRE

PROPERTY OWNER: Doris N Evans	DATE: February 13, 2007	
RESIDENCE ADDRESS: 10 Steven Drive, Voorhees, NJ	INTERVIEWER: P. Austin	,
6. Can you provide the details of any earth disturbing and provide any maps, drawings or design plans if	•	e conducted,
No.		
7. If any earth moving activities were conducted at the empty containers, discolored soils, or foul odors?	ne property, was anything unusual disc	covered such
No.		
8. Has any additional soil/fill been introduced to the No.	property or low lying area filled?	
9. Have any structures been established on the proper to the home?	ty (i.e. new deck or shed) or any exter	nsion added
No, the last construction activity conducted at the pyears ago.	property included building a deck so	ome 28
10. Are there any plans to conduct any landscaping, treat activities in the near or distant future at the propert		onstruction
Not at this time.		
11. Other notes/comments:		
The homeowner's son, David Evans, was identified	l as part of the potable well investig	ation. He

would like to be contacted also for any activities conducted at the above residence.





No.





PROPERTY OWNER: William and Alice Johnston DATE: February 13, 2007 RESIDENCE ADDRESS: 12 Steven Drive, Voorhees, NJ INTERVIEWER: P. Austin		
1. How long have you owned or rented the property in question? The resident reported owning the property for 28 years (since 1979).		
 During the period you have owned your property, have you observed any discolored soils, stressed vegetation or any unusual odors? Homeowner reported Hilliard Creek flowing a number of different colors in the late seventies. It should be noted that Mrs. Johnston is a life-long resident of the Gibbsboro/Voorhees area. 		
3. Has there been any sampling conducted at the property? No, not to date.		
4. If so, who conducted the sampling, for what purposes was this conducted and are the sample results available?N/A.		
 Has there been any remedial, construction, landscaping, clearing or any other earth disturbing activities conducted at the property? Mrs. Johnston reported doing a great deal of gardening in her backyard. There is a deck in her backyard, a shed sitting on railroad ties and a stone walkway. 		
6. Can you provide the details of any earth disturbing activities described above if any were conducted, and provide any maps, drawings or design plans if available?		





PROPERTY OWNER SURVEY QUESTIONNAIRE

PROPERTY OWNER:

William and Alice Johnston

DATE:

February 13, 2007

RESIDENCE ADDRESS:

12 Steven Drive, Voorhees, NJ

INTERVIEWER:

P. Austin

7. If any earth moving activities were conducted at the property, was anything unusual discovered such empty containers, discolored soils, or foul odors?

Foul odors were noticed and colored waters in the creek were observed during the homeowner's youth. It should be noted that the odors may be natural (not a sewerage or solvent smell).

8. Has any additional soil/fill been introduced to the property or low lying area filled?

Only in the garden areas.

9. Have any structures been established on the property (i.e. new deck or shed) or any extension added to the home?


A shed sitting on railroad ties, a stone walkway, a garden and a deck.


10. Are there any plans to conduct any landscaping, tree removal, extensions, and/or other construction activities in the near or distant future at the property?

The homeowner intends on building a patio, planting more shrubs and establishing a bocce ball area.

11. Other notes/comments:


Due to the beaver activities, the homeowner reported having between 40-60% of their backyard being underwater (past the shed), bringing fish and ducks onto the property. The property does sit lower than most other homes. Fish and Game and Camden County have been called numerous times. The main beaver dam is located east of their home and the "red barn" culvert (site of the secondary beaver dam) is located west of their home. Photos available in site files.








PROPERTY OWNER: Terri Hall and Zeb Harris	DATE: February 22, 2007	
RESIDENCE ADDRESS: 14 Steven Drive, Voorhees, NJ	INTERVIEWER: P. Austin	
1. How long have you owned or rented the property in question	on?	
The resident reported purchasing the property in October	2002.	
2. During the period you have owned your property, have you observed any discolored soils, stressed vegetation or any unusual odors?		
The homeowner reported stressed vegetation bordering lake, as well as odors and discoloration (dark brown/black), though it should be noted that it may be natural.		
3. Has there been any sampling conducted at the property?		
No.		
4. If so, who conducted the sampling, for what purposes was this conducted and are the sample results available?		
N/A.		
5. Has there been any remedial, construction, landscaping, clearing or any other earth disturbing activities conducted at the property?		
The property owner installed a fence surrounding the perimeter of the property, three pine trees were removed from the back yard, no pigments were observed.		
6. Can you provide the details of any earth disturbing activities and provide any maps, drawings or design plans if available	es described above if any were conducted,	
No.		





PROPERTY OWNER: Terri Hall and Zeb Harris	DATE: February 22, 2007
RESIDENCE ADDRESS: 14 Steven Drive, Voorhees, NJ	INTERVIEWER: P. Austin
7. If any earth moving activities were conducted at the pempty containers, discolored soils, or foul odors?	property, was anything unusual discovered such
No.	
8. Has any additional soil/fill been introduced to the pro	perty or low lying area filled?
No.	
9. Have any structures been established on the property to the home?	(i.e. new deck or shed) or any extension added
Construction of a deck is planned for 2007.	
10. Are there any plans to conduct any landscaping, tree r activities in the near or distant future at the property?	emoval, extensions, and/or other construction
Plans to remove more trees and conduct additional la	ndscaping in backyard in 2008.
11. Other notes/comments:	
Since the property owners have lived at the property a historical information available.	a relatively short time, there is very little




PROPERTY OWNER: Dennis and Mary Ellen Deichert



DATE: February 13, 2007

GIBBSBORO REMEDIAL INVESTIGATION/FEASIBILITY STUDY

RESIDENCE ADDRESS: 54 W. Clementon Road, (for access to 60 W. Clementon) Gibbsboro, NJ		
1. How long have you owned or rented the property in question?		
The resident reported owning the living on the property for 51 years (since 1956).		
2. During the period you have owned your property, have you observed any discolored soils, stressed vegetation or any unusual odors?		
Mr. Deichert reported Hilliard Creek flowing various colors during his youth.		
3. Has there been any sampling conducted at the property?		
No, property owner has not provided access until recently.		
4. If so, who conducted the sampling, for what purposes was this conducted and are the sample results available?		
N/A.		
5. Has there been any remedial, construction, landscaping, clearing or any other earth disturbing activities conducted at the property?		
No.		
6. Can you provide the details of any earth disturbing activities described above if any were conducted, and provide any maps, drawings or design plans if available?		
No.		





PROPERTY OWNER SURVEY QUESTIONNAIRE

PROPERTY OWNER:

Dennis and Mary Ellen Deichert

DATE:

February 13, 2007

RESIDENCE ADDRESS:

54 W. Clementon Road, Gibbsboro, NJ (for access to 60 W. Clementon)

INTERVIEWER:

P. Austin

7. If any earth moving activities were conducted at the property, was anything unusual discovered such empty containers, discolored soils, or foul odors?

Foul odors and colored waters in the creek were observed during the homeowner's youth.

8. Has any additional soil/fill been introduced to the property or low lying area filled?

The northern banks of Hilliard Creek on the property is built up with imported soils. The soils were imported from excavation activities during the construction of basements in the homes built on the property.

9. Have any structures been established on the property (i.e. new deck or shed) or any extension added to the home?


No.


10. Are there any plans to conduct any landscaping, tree removal, extensions, and/or other construction activities in the near or distant future at the property?

Not at this time.

11. Other notes/comments:

Mr. Deichert recounted a story of a settlement being made with his former next door neighbor, Earl Urban, (62 W. Clementon Rd which is currently a rental property) and Lucas Paints, some time between 1968 and 1970. It appears that Mr. Urban raised geese all of whom died mysteriously after a reported event of dumping in the creek. Mr. Deichert reported flooding to the front steps in 1960. Man-made lake on property was originally 16 feet deep, now only 12 feet deep due to accumulation of leaves, sludge and sediments.








PROPERTY OWNER SURVEY QUESTIONNAIRE

PROPERTY OWNER: 165 Kirkwood Corporation DATE: February 5, 2007	
RESIDENCE ADDRESS: 165 Kirkwood Road, INTERVIEWER: P. Austin Gibbsboro, NJ	
1. How long have you owned or rented the property in question?	
The resident reported owning/renting the property for twenty-two years (since 1985).	
2. During the period you have owned your property, have you observed any discolored soils, stress vegetation or any unusual odors?	ed
No.	
3. Has there been any sampling conducted at the property?	
Sampling was conducted in 2003, 2005 and 2006 by Weston Solutions, Inc. on behalf of The Sherwin-Williams Company.	
4. If so, who conducted the sampling, for what purposes was this conducted and are the sample resavailable?	ults
The sampling was conducted as part of an EPA Removal Action (2003) and part of the Gibbsh Remedial Investigation (2005/2006).)OFO
5. Has there been any remedial, construction, landscaping, clearing or any other earth disturbing activities conducted at the property?	_
Yes. Removal action activities were conducted by Sherwin-Williams in 2003. The top 6-8 inches of the backyard was excavated and backfilled with clean fill and top soil.	ies
6. Can you provide the details of any earth disturbing activities described above if any were conductive.	eted,

Details are included in the files and report for the above-referenced removal action activities.


and provide any maps, drawings or design plans if available?








PROPERTY OWNER:	DATE:	
165 Kirkwood Corporation	February 5, 2007	
RESIDENCE ADDRESS:	INTERVIEWER:	
165 Kirkwood Road, Gibbsboro NJ	P. Austin	
7. If any earth moving activities were conducted at the empty containers, discolored soils, or foul odors?	property, was anything unusual discovered such	
No.		
8. Has any additional soil/fill been introduced to the pro-	operty or low lying area filled?	
Yes – approximately the top 6 to 8 inches of soil were Action activities in 2003.	removed and replaced during the Removal	
9. Have any structures been established on the property to the home?	(i.e. new deck or shed) or any extension added	
No.		
10. Are there any plans to conduct any landscaping, tree removal, extensions, and/or other construction activities in the near or distant future at the property?		
No.		
11. Other notes/comments:		
Water level of Hilliard Creek flowing past property hand beaver dams. Soil and sediment samples collecte and 2006.		







PROPERTY OWNER SURVEY QUESTIONNAIRE

PROPERTY OWNER: Louis and Dina Mueller

DATE: February 26, 2007

RESIDENCE ADDRESS: 1260 Kirkwood Road,

INTERVIEWER: P. Austin

Gibbsboro, NJ

1. How long have you owned or rented the property in question?

The resident reported purchasing the property in 1996 from the Bruin Family Day Camp.

2. During the period you have owned your property, have you observed any discolored soils, stressed vegetation or any unusual odors?

The home owner reported odors from a local sewerage and disposal business that reportedly discharged effluent into the creek.

3. Has there been any sampling conducted at the property?

Homeowner collected four grab surface samples for lead when the property was purchased.

4. If so, who conducted the sampling, for what purposes was this conducted and are the sample results available?


The homeowner reported that all the samples were clean, data could not be found during interview.

5. Has there been any remedial, construction, landscaping, clearing or any other earth disturbing activities conducted at the property?

A UST removal was performed, a basement was also dug out during renovations and construction on the premises, the excavated soils was used to fill low lying areas, additional fill was brought in where needed. No pigmented soils were observed.

6. Can you provide the details of any earth disturbing activities described above if any were conducted, and provide any maps, drawings or design plans if available?

No.





PROPERTY OWNER:	DATE:
Louis and Dina Mueller	February 26, 2007
RESIDENCE ADDRESS: 1260 Kirkwood Road, Gibbsboro	INTERVIEWER: P. Austin
7. If any earth moving activities were conducted at empty containers, discolored soils, or foul odors?	the property, was anything unusual discovered such
No.	
8. Has any additional soil/fill been introduced to the	e property or low lying area filled?
Yes – see response to question 5 above.	
9. Have any structures been established on the properto the home?	erty (i.e. new deck or shed) or any extension added
Yes - a picnic area has been set up in the yard.	
10. Are there any plans to conduct any landscaping, t activities in the near or distant future at the prope	•
No.	
11. Other notes/comments:	
Since the property owners have lived at the prope historical information is available.	rty a relatively short time, there is very little
Kirkwood Lake and Gibbsboro RI soil and sedim	ent samples collected on this property in 2002,








Pl	PROPERTY OWNER: Robert and Dawn Danser DATE: Fe	ebruary 5, 2007
ł .	RESIDENCE ADDRESS: 101 Kirkwood Road, INTERVI	EWER: P. Austin
1.	1. How long have you owned or rented the property in question?	
Tl	The resident reported owning/renting the property for 24.5 years (since	ce 1982).
2.	During the period you have owned your property, have you observed as vegetation or any unusual odors?	ny discolored soils, stressed
Di	Discolored soils were observed on the property during the constructio	n of an addition to the home
3.	3. Has there been any sampling conducted at the property?	
No	No.	·
4.	4. If so, who conducted the sampling, for what purposes was this conduct available?	ed and are the sample results
N/	N/A.	
5.	Has there been any remedial, construction, landscaping, clearing or any other earth disturbing activities conducted at the property?	
Ye	Yes – there was an addition built onto the home.	
6.	6. Can you provide the details of any earth disturbing activities described and provide any maps, drawings or design plans if available?	above if any were conducted,
	A large addition was built onto the back of the house, a deck on the side in closet.	le of the house and a walk-









PROPERTY OWNER:	DATE:	
Robert and Dawn Danser	February 5, 2007	
RESIDENCE ADDRESS:	INTERVIEWER:	
101 Kirkwood Road, Gibbsboro NJ	P. Austin	
To I Kirkwood Road, Gibbsboio IV	1.7 tustin	
7. If any earth moving activities were conducted at the property, was anything unusual discovered such empty containers, discolored soils, or foul odors?		
Discolored soils were noted towards the house during th	e construction of the addition.	
8. Has any additional soil/fill been introduced to the property or low lying area filled?		
9. Have any structures been established on the property (i.e to the home?	e. new deck or shed) or any extension added	
Yes – A large addition was built onto the back of the how walk-in closet.	use, a deck on the side of the house and a	
10. Are there any plans to conduct any landscaping, tree removal, extensions, and/or other construction activities in the near or distant future at the property?		
Not at this time.		
11. Other notes/comments:		
None.		
ATOREO		







PROPERTY OWNER: Stewart J. Lehrfeld DATE: February 5, 2007
RESIDENCE ADDRESS: 16 Steven Drive, Voorhees NJ INTERVIEWER: P. Austin
1. How long have you owned or rented the property in question?
The resident reported owning the property ten years (since 1997).
2. During the period you have owned your property, have you observed any discolored soils, stressed vegetation or any unusual odors?
No.
3. Has there been any sampling conducted at the property?
The resident reported that samples were collected during Spring/Summer 2000.
4. If so, who conducted the sampling, for what purposes was this conducted and are the sample results available?
Homeowner did not know who collected the samples in the 2000 time-frame.
5. Has there been any remedial, construction, landscaping, clearing or any other earth disturbing activities conducted at the property?
A deck and swing/play area has been constructed and mulch has been placed in the garden area.
6. Can you provide the details of any earth disturbing activities described above if any were conducted, and provide any maps, drawings or design plans if available?
No.





PROPERTY OWNER SURVEY QUESTIONNAIRE

PROPERTY OWNER:

DATE:

Stewart J. Lehrfeld

February 5, 2007

RESIDENCE ADDRESS:

INTERVIEWER:

16 Steven Drive, Voorhees NJ

P. Austin

7. If any earth moving activities were conducted at the property, was anything unusual discovered such empty containers, discolored soils, or foul odors?

No.

8. Has any additional soil/fill been introduced to the property or low lying area filled?

The only material introduced to the property is the mulch in the planting area and swing set area.

9. Have any structures been established on the property (i.e. new deck or shed) or any extension added to the home?


The deck and swing set on the property are both relatively new.


10. Are there any plans to conduct any landscaping, tree removal, extensions, and/or other construction activities in the near or distant future at the property?


There is no plan to do any additional work on the property. It should be noted that the property is for sale (there may be a need secure access again if the property is sold by the time the sampling is scheduled).

11. Other notes/comments:

The home is approximately 30 years old; poison ivy abundant in the backyard; geese droppings everywhere in the backyard. After heavy rains, the water level of Hilliard Creek is impacted due to the presence of beavers and beaver dams in the area. Play area approximately 16 feet from the Creek. Garden uses imported soils. Hurricane Floyd flooded backyard approximately 3' shy of patio in 2001-2002. Home is currently for sale.











PROPERTY OWNER: John Jr. & Denise Sweeny	DATE: February 27, 2007	
RESIDENCE ADDRESS: 73 West Road, Gibbsboro NJ	INTERVIEWER: P. Austin	
1. How long have you owned or rented the property in questic	on?	
The resident (Mr. Sweeny, Sr.) reported living at the prope (since 1964). Mr. Sweeny, Jr. is the present owner of the property during the property	roperty, though his father, Mr. Sweeny,	
2. During the period you have owned your property, have you vegetation or any unusual odors?	observed any discolored soils, stressed	
Stressed vegetation was observed (brown spots on lawn), dying trees.		
3. Has there been any sampling conducted at the property?		
No.		
4. If so, who conducted the sampling, for what purposes was t available?	his conducted and are the sample results	
N/A.		
5. Has there been any remedial, construction, landscaping, cle activities conducted at the property?	aring or any other earth disturbing	
Two years ago a wooden deck was built on the property (its excavation).	s construction included a shallow	
6. Can you provide the details of any earth disturbing activitie and provide any maps, drawings or design plans if available	· · · · · · · · · · · · · · · · · · ·	
No.		
	·	






PROPERTY OWNER:	DATE:
John Jr. & Denise Sweeny	February 27, 2007
RESIDENCE ADDRESS: 73 West Road, Gibbsboro NJ,	INTERVIEWER: P. Austin
7. If any earth moving activities were conducted empty containers, discolored soils, or foul odo	at the property, was anything unusual discovered such rs?
A rusted and partially deteriorated steel contai	ner was found on the property.
8. Has any additional soil/fill been introduced to No.	the property or low lying area filled?
9. Have any structures been established on the proto to the home?	operty (i.e. new deck or shed) or any extension added
New deck built on the property 2 years ago.	
10. Are there any plans to conduct any landscaping activities in the near or distant future at the pro	t, tree removal, extensions, and/or other construction perty?
No.	
11. Other notes/comments:	
The homeowner requested that a water sample back on the property, they were trapped years a	be collected from his potable well. The beavers are ago.








PROPERTY OWNER: WB Home Renovations DATE: February 22, 2007		
RESIDENCE ADDRESS: 68 W. Clementon Road, INTERVIEWER: P. Austin Gibbsboro, NJ		
1. How long have you owned or rented the property in question?		
The resident reported purchasing the property in October 2005.		
2. During the period you have owned your property, have you observed any discolored soils, stressed vegetation or any unusual odors?		
No.		
3. Has there been any sampling conducted at the property?		
Not to the knowledge of the property owner.		
4. If so, who conducted the sampling, for what purposes was this conducted and are the sample results available?		
N/A.		
5. Has there been any remedial, construction, landscaping, clearing or any other earth disturbing activities conducted at the property?		
Most of the work completed at the property was done to the home interior and exterior. Some landscaping and planting of grass.		
6. Can you provide the details of any earth disturbing activities described above if any were conducted, and provide any maps, drawings or design plans if available?		
No.		





PROPERTY OWNER: WB Home Renovations	DATE: February 22, 2007
RESIDENCE ADDRESS: 68 W. Clementon Road, Gibbsboro, NJ	INTERVIEWER: P. Austin
7. If any earth moving activities were conducted at the empty containers, discolored soils, or foul odors?	ne property, was anything unusual discovered such
No.	
8. Has any additional soil/fill been introduced to the	property or low lying area filled?
No.	
9. Have any structures been established on the proper to the home?	rty (i.e. new deck or shed) or any extension added
No.	
10. Are there any plans to conduct any landscaping, tre activities in the near or distant future at the propert	
No.	
11. Other notes/comments:	
Since the property owners have owned the propert there is very little historical information available. neighbors.	









TROPERT I OWNER. Raymond & Catolyn Dansky DATE: Teoluary 3, 2007
RESIDENCE ADDRESS: 18 Steven Drive, Voorhees NJ INTERVIEWER: P. Austin
1. How long have you owned or rented the property in question?
The resident reported owning the property for twenty-six years (since 1981).
2. During the period you have owned your property, have you observed any discolored soils, stressed vegetation or any unusual odors?
Patches of stressed vegetation observed on the property, the homeowner reported awful odors coming from the creek, no staining or discolored soils.
3. Has there been any sampling conducted at the property?
No.
4. If so, who conducted the sampling, for what purposes was this conducted and are the sample results available?
N/A.
5. Has there been any remedial, construction, landscaping, clearing or any other earth disturbing activities conducted at the property?
Worker shed/red barn constructed by homeowner some 20 years ago. A gazebo on the property was built, but no earth moving activities were required.
6. Can you provide the details of any earth disturbing activities described above if any were conducted, and provide any maps, drawings or design plans if available?
No.



extend 20 feet into the Creek.





PROPERTY OWNER SURVEY QUESTIONNAIRE

PROPERTY OWNER:	DATE:
Raymond & Carolyn Bansky	February 5, 2007
RESIDENCE ADDRESS: 18 Steven Drive, Voorhees NJ	INTERVIEWER: P. Austin
7. If any earth moving activities were conducted at the prempty containers, discolored soils, or foul odors?	roperty, was anything unusual discovered such
No.	
8. Has any additional soil/fill been introduced to the prop	perty or low lying area filled?
No.	
9. Have any structures been established on the property (to the home?	i.e. new deck or shed) or any extension added
Only the red barn and gazebo were constructed.	
10. Are there any plans to conduct any landscaping, tree reactivities in the near or distant future at the property?	emoval, extensions, and/or other construction
No.	
11. Other notes/comments:	
<u> </u>	
There is a low voltage utility line running to the red shed	<u> </u>
any issues with the beavers, (elevation on the property high	ther than neighbors). Property line reported to

This residence has the red barn (covered bridge) with the culvert leading to the main body of Kirkwood Lake in their backyard. The beavers constructed a dam in that culvert that caused additional flooding upstream.

Please note that this property is downstream of the main beaver dam that is constructed behind the age-restricted community in Glenview Way East.